

Certificate of Compliance

This is to certify that the Clean Room facilities at

Sabre Medical

Address:

Unit 19-11 Chaplin Drive, LANE COVE WEST NSW 2066

Location:

Clean Room

Was tested to the relevant **AS ISO 14644.1:2017** on

20/06/2019

and complied with the requirements for a

ISO 5

ISO 6

ISO 7

ISO 8

ISO 9

Certificate No:

SM625/19

Recommended Next Test:

June 2020

Accredited Signature:



NATA Accredited Laboratory Number 3098
PO BOX 4469 North Rocks NSW 2151
Phone: 1300 004 237 | Mobile: 0488 400 072
Email: independentairflow@optusnet.com.au
www.independentairflow.com.au



Independent
Air Flow
Services

ACCREDITED FOR COMPLIANCE WITH ISO/IEC 17025. TESTING ACCREDITATION NO: 3098