

# Certificate of Compliance

This is to certify that the Clean Room facilities at **Sabre Medical**

Address: **Unit 1 9-11 Chaplin Drive, LANE COVE WEST NSW 2066**

Location: **Unit 1 | Clean Room**

Was tested to the relevant **AS ISO 14644.1:2017** on **12th June 2020**

and complied with the requirements for a

ISO 5

ISO 6

ISO 7

ISO 8

ISO 9

Certificate No: **SM415/20**

Recommended Next Test: **June 2021**

Accredited Signature:   
D. Hazell



NATA Accredited Laboratory Number 3098  
PO BOX 4469 North Rocks NSW 2151  
Phone: 1300 004 237 | Mobile: 0488 400 072  
Email: [independentairflow@optusnet.com.au](mailto:independentairflow@optusnet.com.au)  
[www.independentairflow.com.au](http://www.independentairflow.com.au)



ACCREDITED FOR COMPLIANCE WITH ISO/IEC 17025. TESTING ACCREDITATION NO: 3098